

SUBARU P1498: EGR SOLENOID VALVE SIGNAL #4 CIRCUIT MALFUNCTION (LOW INPUT)

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$250-\$350
Can I Still Drive?	:	Yes (Short-term only)

What Are The Symptoms Of The Subaru P1498 Code?

Improper idling. Poor driving performance. Engine breathing.

What Are The Potential Causes Of The Subaru P1498 Code?

- Wiring harness between EGR valve and power supply needs repair
- Wiring harness between ECM and EGR valve connector needs repair
- Poor contact in the ECM and EGR valve connector
- Defective EGR valve

Reference Sources

[DIAGNOSTIC PROCEDURE WITH DIAGNOSTIC TROUBLE CODE FOR P1498](#) - Pages 159-160.