		OVERVIEW
Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$200

What Does The Subaru P1502 Code Mean?

Engine started, ECT sensor signal less than 200°F, and the PCM detected an unexpected "low" voltage condition on the Radiator Fan Relay control circuit during the CCM Rationality test.

How Can You Fix The Subaru P1502 Code?

Check any other DTC on display

Reference Sources

<u>Diagnostics Chart with Trouble Codes for P1502</u> - Pages 236-238.

