

## SUBARU P1515: ISC SOLENOID VALVE SIGNAL NO. 3 CIRCUIT MALFUNCTION (HIGH INPUT)

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Advanced</div></div>
Repair Cost	:	\$120-\$500
Can I Still Drive?	:	Yes

### What Does The Subaru P1515 Code Mean?

Key on or engine running; and the PCM detected an unexpected "low" condition on the IAC solenoid Signal 3 circuit during the test.

### How Can You Fix The Subaru P1515 Code?

- Check any other DTC on display
- Check ground circuit for ECM
- Check harness between ECM and idle control solenoid valve connector

### Reference Sources

[DIAGNOSTIC PROCEDURE WITH DIAGNOSTIC TROUBLE CODE FOR P1515](#) - Page 163.