

SUBARU P1544: EXHAUST GAS TEMPERATURE TOO HIGH

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$200-\$300
Can I Still Drive?	:	No

What Are The Symptoms Of The Subaru P1544 Code?

Erroneous idling. Poor driving performance.

What Are The Potential Causes Of The Subaru P1544 Code?

- Check any other DTC on display
- Check exhaust system

Reference Sources

[Testing and Inspection for P1544](#) - 2004 FORESTER SERVICE MANUAL, pages 213-214.