

SUBARU P1574: KEY COMMUNICATION FAILURE

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Subaru P1574 Code Mean?

Communication failure between key and body integrated unit.

What Are The Potential Causes Of The Subaru P1574 Code?

- Faulty ignition keys (transponders)
- Faulty body integrated unit. (Register all ignition keys (transponders))

Reference Sources

[Diagnostic Trouble Code \(DTC\) Detecting Criteria for P1574](#) - Page 192