

## SUBARU P1704: 2-4 BRAKE TIMING CONTROL SOLENOID VALVE CIRCUIT MALFUNCTION

### OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$60-\$420
Can I Still Drive?	:	Yes (Short-term only)

### What Does The Subaru P1704 Code Mean?

Engine started, vehicle driven to a speed of over 3 mph, and the PCM detected an unexpected voltage condition on the A/T 2-4 Brake Timing Control Solenoid duty cycle circuit during the CCM test.

### What Are The Potential Causes Of The Subaru P1704 Code?

Check 2-4 brake timing control solenoid valve circuit

### Reference Sources

[Subaru Impreza Repair Manual for P1704](#) - Page 667.