

SUBARU P1706: AT VEHICLE SPEED SENSOR CIRCUIT MALFUNCTION (REAR WHEEL)

OVERVIEW

| | | |
|----------------------|---|------------------------------------|
| Severity | : | <div><div>High</div></div> |
| DIY Difficulty Level | : | <div><div>Intermediate</div></div> |
| Repair Cost | : | \$100-\$350 |
| Can I Still Drive? | : | No |

What Does The Subaru P1706 Code Mean?

Input signal circuit of TCM is open or shorted.

What Are The Symptoms Of The Subaru P1706 Code?

Shifting quality malfunction

What Are The Potential Causes Of The Subaru P1706 Code?

Rear vehicle speed sensor malfunction, open or shorted input circuit, ground, power supply.

Reference Sources

[Diagnostic Procedure with Diagnostic Trouble Code for P1706](#) - Pages 89-91.