SUBARU P1707: AT AWD SOLENOID VALVE CIRCUIT MALFUNCTION		
		OVERVIEW
Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	Yes (Short-term only)

What Does The Subaru P1707 Code Mean?

Output signal circuit of transfer duty solenoid is open or shorted. Tight corner braking phenomenon occurs. Front wheel slips on the slippery road.

What Are The Potential Causes Of The Subaru P1707 Code?

Transfer duty solenoid is faulty or output signal circuit is open or shorted.

Reference Sources

<u>Diagnostic Procedure with Diagnostic Trouble Code for P1707</u> - Pages 92-94.

