

## SUBARU P1710: TORQUE CONVERTER TURBINE 2 SPEED SIGNAL CIRCUIT MALFUNCTION

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	<b>Yes</b> (Short-term only)

### What Does The Subaru P1710 Code Mean?

Input signal circuit of TCM is open or shorted. Excessive shift shock felt. Does not shift to 5th.

### What Are The Potential Causes Of The Subaru P1710 Code?

Turbine speed sensor 2 malfunction, open or shorted input circuit, ground, power supply

### Reference Sources

[ProDemand Automotive Repair Information](#) - 2005 Subaru Outback R