

## SUBARU P1711: ENGINE TORQUE CONTROL SIGNAL NO. 1 CIRCUIT MALFUNCTION

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

### What Does The Subaru P1711 Code Mean?

Engine started, vehicle driven to a speed of over 20 mph, and the PCM detected an unexpected voltage condition on the Engine Torque Control Signal 1 circuit during the CCM continuous test.

### How Can You Fix The Subaru P1711 Code?

- Check input signal for ECM
- Check poor contact
- Check harness between ECM and TCM connector

### Reference Sources

[DIAGNOSTIC PROCEDURE WITH DIAGNOSTIC TROUBLE CODE FOR P1711](#) - Pages 177-178.