

SUBARU P1844: TRANSMISSION FLUID PRESSURE SENSOR SWITCH E CIRCUIT

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$170-\$300
Can I Still Drive?	:	No

What Does The Subaru P1844 Code Mean?

High & low reverse clutch oil pressure switch malfunction. Excessive shift shock felt.

What Are The Potential Causes Of The Subaru P1844 Code?

Open or shorted H& LR/C fluid pressure switch or switch malfunction

Reference Sources

- [Technical Service Bulletin 16-86-12 for P1844](#) - 2013MY Legacy, Outback and Tribeca
- [Technical Service Bulletin 16-80-11R for P1844](#) - 2010~13MY Legacy, Outback & Tribeca