

TOYOTA B1562: XM TUNER DISCONNECTED (BURST MODE)

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$300-\$600
Can I Still Drive?	:	Yes (Short-term only)

What Does The Toyota B1562 Code Mean?

When the master unit deletes the satellite radio tuner from the system components device list due to an AVC-LAN plus communication error.

What Are The Potential Causes Of The Toyota B1562 Code?

- AVC-LAN plus circuit between display and navigation assembly and stereo component tuner assembly
- Stereo component tuner assembly
- Navigation receiver assembly

Reference Sources

[Toyota B1562](#), DTCDECODE.