

TOYOTA B1593: NO RESPONSE FROM STEREO COMPONENT AMPLIFIER

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Toyota B1593 Code Mean?

Within the time-out period, there was no response from the stereo component amplifier assembly to the following requests from the master unit: System inspection request System inspection result request Diagnostic memory request

What Are The Potential Causes Of The Toyota B1593 Code?

- Stereo component amplifier assembly power source circuit
- AVC-LAN circuit between navigation receiver assembly and stereo component amplifier assembly
- Navigation receiver assembly
- Stereo component amplifier assembly

Reference Sources

[Toyota B1593](#), DTCDECODE.