

## TOYOTA B159F: NO RESPONSE FROM XM TUNER

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	<b>Yes</b> (Short-term only)

### What Does The Toyota B159F Code Mean?

Within the time-out period, there was no response from the stereo component tuner assembly to the following requests from the master unit: System inspection request System inspection result request Diagnostic memory request.

### What Are The Potential Causes Of The Toyota B159F Code?

- Stereo component tuner assembly power source circuit
- AVC-LAN circuit between navigation receiver assembly and stereo component tuner assembly
- Navigation receiver assembly
- Stereo component tuner assembly

### Reference Sources

[Toyota B159F](#), DTCDECODE.