TOYOTA P1012: OCV FOR VVTL CLOSE MALFUNCTION (BANK 1)		
OVERVIEW		
Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$200
Can I Still Drive?	:	Yes (Short-term only)

What Does The Toyota P1012 Code Mean?

In the condition that the water temperature is $60 \, ^{\circ}\text{C}$ or more, the engine speed is $6,000 \, \text{rpm}$ or more, and the oil pressure switch OFF for 1 sec. or more.

What Are The Potential Causes Of The Toyota P1012 Code?

- Open or short in OCV circuit
- OCV for VVT-L
- Oil pressure switch for VVT-L
- ECM

Reference Sources

Toyota P1012, DTCDECODE.

