

TOYOTA P1349: VVT SYSTEM MALFUNCTION

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$150-\$450
Can I Still Drive?	:	No

What Does The Toyota P1349 Code Mean?

Condition (a) or (b) continues for after the engine is warmed up and engine speed at 400 ~ 4,000 rpm : (a) Valve timing does not change from of current valve timing (b) Current valve timing is fixed.

What Are The Potential Causes Of The Toyota P1349 Code?

- Valve timing
- Oil control valve
- VVT controller assembly
- ECM

Reference Sources

- [Testing and Inspection for P1349](#) - 2000 MR2
- [Technical Service Bulletin](#) - 2000 – 2002 Corolla, Celica, MR2 Spyder, and ECHO