

## What Does The Toyota P1349 Code Mean?

Condition (a) or (b) continues for after the engine is warmed up and engine speedat  $400 \sim 4,000$  rpm :(a) Valve timing does not change from of current valve timing(b) Current valve timing is fixed.

## What Are The Potential Causes Of The Toyota P1349 Code?

- Valve timing
- Oil control valve
- VVT controller assembly
- ECM

## **Reference Sources**

- Testing and Inspection for P1349 2000 MR2
- Technical Service Bulletin 2000 2002 Corolla, Celica, MR2 Spyder, and ECHO

