

TOYOTA P3005: HIGH VOLTAGE FUSE SNAPPED

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$60-\$250
Can I Still Drive?	:	Yes

What Does The Toyota P3005 Code Mean?

Although interlock switch is connected, voltage of battery block No. 10 is less than specified.

What Are The Potential Causes Of The Toyota P3005 Code?

- High voltage fuse
- Power cable

Reference Sources

[Prius Repair Manual for P3005](#) - Page 286.