

TOYOTA P3105: BATTERY SMART UNIT COMMUNICATION CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$80-\$250
Can I Still Drive?	:	Yes

What Does The Toyota P3105 Code Mean?

Problem in serial communication between the battery smart unit and HV control ECU (1 trip).

What Are The Potential Causes Of The Toyota P3105 Code?

- Wire harness or connector
- HV control ECU
- Battery pack wire
- Battery smart unit

Reference Sources

[Prius Repair Manual for P3105](#) - Pages 199-200.