

VOLKSWAGEN P1004: TORQUE DIFFERENCE CYLINDER 1 LIMITING VALUE EXCEEDED

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$350-\$850
Can I Still Drive?	:	No

What Does The Volkswagen P1004 Code Mean?

Engine running ECM in closed loop ECT > 50 °C Time since engine start > 30 Sec.

Reference Sources

- [VW Jetta SportWagen Quick Reference Specification Book](#) - 2012, Volkswagen Group of America, page 126.
- [VW Passat Quick Reference Specification Book](#) - 2012, Volkswagen Group of America, page 146.
- [VW Golf & GTI Quick Reference Specification Book](#) - 2012, Volkswagen Group of America, page 216.
- [VW Jetta & GLI Quick Reference Specification Book](#) - 2012, Volkswagen Group of America, page 186.
- [VW Beetle/Beetle Cabrio Quick Reference Specification Book](#) - 2013, Volkswagen Group of America, page 156.
- [VW Golf & GTI Quick Reference Specification Book](#) - 2014, Volkswagen Group of America, page 46.
- [VW Beetle/Beetle Cabrio Quick Reference Specification Book](#) - 2014, Volkswagen Group of America, page 16.
- [VW Jetta & GLI Quick Reference Specification Book](#) - 2014, Volkswagen Group of America,

page 29.

- [VW Passat Quick Reference Specification Book](#) - 2014, Volkswagen Group of America, page 36.