

VOLKSWAGEN P1005: TORQUE DIFFERENCE CYLINDER 2 LIMITING VALUE EXCEEDED

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$350-\$850
Can I Still Drive?	:	No

What Does The Volkswagen P1005 Code Mean?

Engine running ECM in closed loop ECT > 50 °C Time since engine start > 30 Sec.

What Are The Potential Causes Of The Volkswagen P1005 Code?

- Injector(s) leaky/dirty
- Compression loss

How Can You Fix The Volkswagen P1005 Code?

- Check injector(s)
- Check compression

Reference Sources

- [VW Jetta SportWagen Quick Reference Specification Book](#) - 2012, Volkswagen Group of America, page 126.
- [VW Passat Quick Reference Specification Book](#) - 2012, Volkswagen Group of America, page 146.
- [VW Golf & GTI Quick Reference Specification Book](#) - 2012, Volkswagen Group of America, page 217.
- [VW Jetta & GLI Quick Reference Specification Book](#) - 2012, Volkswagen Group of America,

page 186.

- [VW Beetle/Beetle Cabrio Quick Reference Specification Book](#) - 2013, Volkswagen Group of America, page 156.
- [VW Golf & GTI Quick Reference Specification Book](#) - 2014, Volkswagen Group of America, page 47.
- [VW Beetle/Beetle Cabrio Quick Reference Specification Book](#) - 2014, Volkswagen Group of America, page 16.
- [VW Jetta & GLI Quick Reference Specification Book](#) - 2014, Volkswagen Group of America, page 29.
- [VW Passat Quick Reference Specification Book](#) - 2014, Volkswagen Group of America, page 36.