## VOLKSWAGEN P1410: TANK VENTILATION VALVE CIRCUIT SHORT TO B+: OVERVIEW Severity: Medium DIY Difficulty Level: Intermediate Repair Cost: \$100-\$200 Can I Still Drive?: Yes (Short-term only)

## What Does The Volkswagen P1410 Code Mean?

Key on or engine running; and the ECM detected a too high or too low voltage level in the tank ventilation valve circuit.

## What Are The Potential Causes Of The Volkswagen P1410 Code?

- EVAP canister purge regulator valve has failed
- Activation wire is shorting to positive
- EVAP canister system has an improper or broken seal
- Evaporative Emission (EVAP) canister purge regulator valve 1 is faulty
- Leak Detection Pump (LDP) is faulty
- Fuel filler cap is not properly closed
- Lock ring on fuel pump not tightened
- Hoses between EVAP canister and purge regulator valve have failed
- ECM has failed

## **Reference Sources**

Volkswagen P1410, DTCDECODE.

