# VOLKSWAGEN P1436: A/C EVAPORATOR TEMPERATURE (ACET) CIRCUIT LOW INPUT

#### **OVERVIEW**

Severity : Medium

DIY Difficulty Level : Intermediate

**Repair Cost** : \$300-\$450

**Can I Still Drive?** : Yes (Short-term only)

### What Does The Volkswagen P1436 Code Mean?

Key on or engine running; and the ECM detected the ACET signal was less than the self-test minimum amount of in the self-test.

## What Are The Potential Causes Of The Volkswagen P1436 Code?

- ACET signal circuit shorted to sensor ground (return)
- ACET signal circuit shorted to chassis ground
- ACET sensor is damaged or has failed
- Check activation of Secondary Air Injection (AIR) Pump Relay
- ECM has failed

#### **Reference Sources**

Volkswagen P1436, DTCDECODE.

