

VOLKSWAGEN P1780: TORQUE WITHDRAWAL FAULTY

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$200
Can I Still Drive?	:	Yes (Short-term only)

What Does The Volkswagen P1780 Code Mean?

Torque reduction requested by TCM

Reference Sources

[Volkswagen P1780](#), DTCDECODE.