

What Does The Volkswagen P3081 Code Mean?

Maximum reference temperature, 60 °C

What Are The Potential Causes Of The Volkswagen P3081 Code?

- Let engine warm up
- Engine Coolant Temperature (ECT) Sensor
- Check the wiring for an open circuit, a short circuit to each other, Battery (+), or Ground (GND)
- Repalce ECM

Reference Sources

Volkswagen P3081, DTCDECODE.

