

VOLKSWAGEN P310A: LOW FUEL PRESSURE REGULATION COOLANT FUEL PRESSURE OUTSIDE SPECIFICATION

OVERVIEW

| | | |
|----------------------|---|-------------------------|
| Severity | : | <div>High</div> |
| DIY Difficulty Level | : | <div>Intermediate</div> |
| Repair Cost | : | \$200-\$300 |
| Can I Still Drive? | : | Yes |

What Does The Volkswagen P310A Code Mean?

Engine started, battery voltage must be at least 11.5v, all electrical components must be off, the ground between the engine and the chassis must be well connected, the exhaust system must be properly sealed between the catalytic converter and the cylinder.

What Are The Potential Causes Of The Volkswagen P310A Code?

- Fuel Pressure Regulator Valve faulty
- Fuel Pressure Sensor faulty
- Fuel Pump (FP) Control Module faulty
- Fuel pump faulty
- Low fuel

Reference Sources

[Volkswagen P310A](#), DTCDECODE.