

VOLKSWAGEN P310B: LOW FUEL PRESSURE REGULATION FUEL PRESSURE FLUCTUATES

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$200-\$300
Can I Still Drive?	:	Yes (Short-term only)

What Does The Volkswagen P310B Code Mean?

Engine started, battery voltage must be at least 11.5v, all electrical components must be off, the ground between the engine and the chassis must be well connected, the exhaust system must be properly sealed between the catalytic converter and the cylinder

What Are The Potential Causes Of The Volkswagen P310B Code?

- Fuel Pressure Regulator Valve faulty
- Fuel Pressure Sensor faulty
- Fuel Pump (FP) Control Module faulty
- Fuel pump faulty
- Low fuel

Reference Sources

[Volkswagen P310B](#), DTCDECODE.