

# VOLKSWAGEN P3262: EXHAUST (BANKS 1 AND 2) OXYGEN SENSORS BEHIND CATALYTIC CONVERTER SWPPED

## OVERVIEW

<b>Severity</b>	:		High
<b>DIY Difficulty Level</b>	:		Intermediate
<b>Repair Cost</b>	:	\$100-\$300	
<b>Can I Still Drive?</b>	:	<b>Yes</b>	(Short-term only)

## What Does The Volkswagen P3262 Code Mean?

Engine started, battery voltage must be at least 11.5v, all electrical components must be off, the ground between the engine and the chassis must be well connected, the exhaust system must be properly sealed between the catalytic converter and the cylinder

## What Are The Potential Causes Of The Volkswagen P3262 Code?

- O2 harness connectors are swapped
- O2 wiring is crossed inside the harness
- O2 wires are crossed at 104-pin connector
- Connector coding and color mixed with correct catalytic converter

## Reference Sources

[Volkswagen P3262](#), DTCDECODE.