

ACURA B1001: MULTIPLEX INTEGRATED CONTROL UNIT (MICU) INTERNAL ERROR

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Acura B1001 Code Mean?

PCM or F-CAN loss of communication, B-CAN loss of communication

What Are The Potential Causes Of The Acura B1001 Code?

- Faulty battery or charging system
- PCM or F-CAN loss of communication errors
- Poor connections or loose pins at all connectors related to the circuit.
- MICU Internal (CPU)
- PCM

Reference Sources

[Accessories & Equipment Multiplex Integrated Control System Service Manual for B1001](#) - 2004 Acura TSX, page 40.