

# Acura B1005: MICU Lost Communication with Relay Control Module (RM Message)

## OVERVIEW

Severity

:

Medium

DIY Difficulty Level

:

Intermediate

Repair Cost

:

\$75-\$200

Can I Still Drive?

:

**Yes** (Short-term only)

## What Does The Acura B1005 Code Mean?

This code indicates PCM or F-CAN loss of communication, B-CAN system loss of communication.

**NOTE:** If you are troubleshooting multiple DTC's, be sure to follow the instructions in B-CAN system diagnosis Test Mode A.

## What Are The Potential Causes Of The Acura B1005 Code?

Below are some possible causes of this DTC:

- Faulty battery or charging system
- PCM or F-CAN poor connections or loose pins at connectors
- B-CAN system poor connections or loose pins at connectors
- Faulty relay control module

## Reference Sources

[Accessories & Equipment Multiplex Integrated Control System Service Manual for B1005](#) - 2004 Acura TSX, pages 40-41.