

ACURA B1064: RELAY CONTROL MODULE LOST COMMUNICATION WITH DRIVER'S MPCS UNIT (DOORSW MESSAGE)

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Acura B1064 Code Mean?

Poor communication between the Relay Control Module and the Driver's MPCS Unit. **NOTE:** If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B1064 Code?

- Loose or poor connections between the Relay Control Module and the Driver's MPCS Unit
- Blown fuse in the main under-hood fuse box
- Blown fuse in the under-dash fuse/relay box
- "Open" or "Short" to ground at the Relay Control Unit
- "Open" or "Short" to ground at the Driver's MPCS Unit
- Faulty Relay Control Unit
- Faulty Driver's MPCS Unit

Reference Sources

[Acura B1064](#), DTCDECODE.