MALFUNCTION		
		OVERVIEW
Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$150
Can I Still Drive?	:	Yes

## What Does The Acura B1075 Code Mean?

Poor communication between the Combination Switch Control Unit and the Relay Control Module or between the Combination Switch Control Unit and the MICU

## What Are The Potential Causes Of The Acura B1075 Code?

- Short in the WHT wire between the Combination Switch Control Unit and the Relay Control Module (H/L BACK-UP line) or between the Combination Switch Control Unit and the MICU
- Open GND circuit
- Blown fuse in the main under-hood fuse box
- Blown fuse in the under-dash fuse/relay box
- "Open" or "Short" to ground at the Relay Control Unit
- "Open" or "Short" to ground at the Combination Control Unit.
- Faulty Relay Control Unit
- Faulty Combination Control Unit

## **Reference Sources**

Acura B1075, DTCDECODE.

