

ACURA B1079: DAYTIME RUNNING LIGHTS MALFUNCTION

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	Yes (Short-term only)

What Does The Acura B1079 Code Mean?

This code indicates headlight high beam malfunction, one or both.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B1079 Code?

Below are some possible causes of this DTC:

- Faulty fuse and/or bulb
- Loose or poor connections
- Poor ground
- "Open" or "Short"
- Faulty daytime running light control unit
- Faulty relay control module

Reference Sources

[Acura B1079](#), DTCDECODE.