

ACURA B1135: RIGHT REAR POWER WINDOW MOTOR PULSE B ERROR

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Advanced</div></div>
Repair Cost	:	\$250-\$510
Can I Still Drive?	:	Yes

What Does The Acura B1135 Code Mean?

Inoperative or intermittent operation of the right rear power window motor. If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B1135 Code?

- Loose or poor connections between the window motor and switch
- "Open" between right rear power window switch and ground
- "Open" or "Short" between the window motor and switch
- Faulty right rear power window switch
- Faulty right rear power window motor

Reference Sources

[Acura B1135](#), DTCDECODE.