

ACURA B1150: COMMUNICATION BUS LINE ERROR

OVERVIEW

| | | |
|----------------------|---|------------------------------------|
| Severity | : | <div><div>Medium</div></div> |
| DIY Difficulty Level | : | <div><div>Intermediate</div></div> |
| Repair Cost | : | \$90-\$150 |
| Can I Still Drive? | : | Yes |

What Does The Acura B1150 Code Mean?

Poor Bus line communication.

What Are The Potential Causes Of The Acura B1150 Code?

- Loose or poor connections at the MICU and B-CAN connected units
- Faulty gauge control module

Reference Sources

[Accessories & Equipment Multiplex Integrated Control System Service Manual for B1150](#) - 2004
Acura TSX, pages 39-40.