

ACURA B1166: GAUGE CONTROL MODULE LOST COMMUNICATION WITH ADAPTIVE FRONT LIGHTING CONTROL UNIT (AFS MESSAGE)

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Acura B1166 Code Mean?

Poor communication between the gauge control module and adaptive front lighting control unit.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B1166 Code?

- Perform the adaptive front lighting control unit input test
- Perform the gauge control module input test
- Blown fuse
- Poor connections or loose terminals between the gauge control module and the adaptive front lighting control unit
- Faulty adaptive front lighting control unit
- Faulty gauge control module

Reference Sources

[Acura B1166](#), DTCDECODE.