

ACURA B1169: GAUGE CONTROL MODULE LOST COMMUNICATION WITH THE PCM (A/T MESSAGE)

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes (Short-term only)

What Does The Acura B1169 Code Mean?

This code indicates poor communication between the Gauge Control Module and the PCM.

What Are The Potential Causes Of The Acura B1169 Code?

Below are some possible causes of this DTC:

- Check for any Fuel and Emissions Systems DTCs first, then retest
- Loose or poor connection between the Gauge Control Module and the PCM
- "Open" or "Short" between Gauge Control Module and PCM
- Update the PCM if it does not have the latest software.
- Faulty Gauge Control Module
- Faulty PCM

Reference Sources

[Acura B1169](#), DTCDECODE.