ACURA B1250: COMMUNICATION BUS LINE ERROR		
		OVERVIEW
Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$90-\$150
Can I Still Drive?	:	Yes

What Does The Acura B1250 Code Mean?

Poor Bus line communication

What Are The Potential Causes Of The Acura B1250 Code?

Loose or poor connections at the MICU and B-CAN connected units

Reference Sources

Accessories & Equipment Multiplex Integrated Control System Service Manual for B1250 - 2004 Acura TSX, pages 39-40.

