

ACURA B1275: COMBINATION LIGHT SWITCH OFF POSITION CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$150-\$350
Can I Still Drive?	:	Yes

What Does The Acura B1275 Code Mean?

Headlamps and/or riding lights are inoperable or intermittent.

What Are The Potential Causes Of The Acura B1275 Code?

- Loose or poor connections
- "Open" or "short" in the combination light switch terminals
- Faulty combination switch control unit, replace the wiper/washer switch
- Faulty Combination Light Switch

Reference Sources

[Acura B1275](#), DTCDECODE.