ACURA B1276: COMBINATION LIGHT SWITCH PARKING (SMALL) POSITION CIRCUIT MALFUNCTION OVERVIEW Severity : High DIY Difficulty Level : Advanced

Repair Cost : \$150-\$350

Can I Still Drive? : Yes (Short-term only)

What Does The Acura B1276 Code Mean?

This code indicates that headlamps and/or riding lights are inoperable or intermittent.

What Are The Potential Causes Of The Acura B1276 Code?

Below are some possible causes of this DTC:

- Loose or poor connections
- "Open" or "short" in the combination light switch terminals
- Faulty combination switch control unit, replace the wiper/washer switch
- Faulty Combination Light Switch

Reference Sources

Acura B1276, DTCDECODE.

