ACURA B1352: POWER TAILGATE CONTROL UNIT INTERNAL (EEPROM) ERROR

OVERVIEW

Severity : Medium

DIY Difficulty Level : Intermediate

Repair Cost : \$75-\$200

Can I Still Drive? : Yes

What Does The Acura B1352 Code Mean?

Inoperable or intermittent power tailgate.

What Are The Potential Causes Of The Acura B1352 Code?

- Loose or poor connections between the power tailgate control unit and the MICU
- Fauty Power Tailgate Control Unit

Reference Sources

POWER TAILGATE TROUBLESHOOTING for B1352 - Page 1.

