

ACURA B1352: POWER TAILGATE CONTROL UNIT INTERNAL (EEPROM) ERROR

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Acura B1352 Code Mean?

Inoperable or intermittent power tailgate.

What Are The Potential Causes Of The Acura B1352 Code?

- Loose or poor connections between the power tailgate control unit and the MICU
- Faulty Power Tailgate Control Unit

Reference Sources

[POWER TAILGATE TROUBLESHOOTING for B1352](#) - Page 1.