ACURA B1375: DRIVER'S DOOR POWER TAILGATE SWITCH CIRCUIT MALFUNCTION OVERVIEW

Severity : Medium

DIY Difficulty Level : Intermediate

Repair Cost : \$75-\$200

Can I Still Drive? : Yes

What Does The Acura B1375 Code Mean?

Poor communication between the drivers door power tailgate switch and the power tailgate control unit. (Possible Short)

NOTE: If the power tailgate motor does not operate, test the motor first.

What Are The Potential Causes Of The Acura B1375 Code?

- Loose or poor connections between the power tailgate control unit and the driver's door power tailgate switch
- "Short" between the power tailgate control unit and body ground
- Faulty Power Tailgate Control Unit
- Faulty Driver's Door Power Tailgate Switch

Reference Sources

POWER TAILGATE TROUBLESHOOTING for B1375 - Pages 1-3.

