

## ACURA B1605: KEYLESS ACCESS CONTROL UNIT LOST COMMUNICATION WITH MICU (MICU MESSAGE)

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	<b>Yes</b> (Short-term only)

### What Does The Acura B1605 Code Mean?

This code indicates Poor communication between the keyless access control unit and MICU.

#### NOTE:

- If DTCs [B1055](#), [B1157](#), [B1255](#), [B1806](#), B2107, and B2155 are also perform the MICU input test.
- If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

### What Are The Potential Causes Of The Acura B1605 Code?

Most common cause: Faulty keyless access control unit

### Reference Sources

[Acura B1605](#), DTCDECODE.