

ACURA B1786: HANDSFREELINK CONTROL UNIT LOST COMMUNICATION WITH GAUGE CONTROL MODULE (VEHINFO FRAME)

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Acura B1786 Code Mean?

Poor communication with the HandsFreeLink Control Unit and the Gauge Control Module .

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B1786 Code?

- Poor connections or loose terminals at the HandsFreeLink control unit
- Blown fuse in the under-dash fuse/relay box
- "Open" in the wire(s) between body ground and the gauge control module
- "Open" in the wire between power tailgate control unit and the gauge control module
- Faulty HandsFreeLink control unit
- Faulty Gauge Control Module

Reference Sources

[Acura B1786](#), DTCDECODE.