ACURA B1844: POWER SEAT SLIDE SWITCH CIRCUIT MALFUNCTION		
		OVERVIEW
Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$75-\$300
Can I Still Drive?	:	Yes

What Does The Acura B1844 Code Mean?

Power Seat Slide Switch Circuit malfunction.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B1844 Code?

- Check for loose or poor connections
- "Short" to ground
- Faulty Lower Seat Control Unit
- Power Seat Adjustment Switch

Reference Sources

Acura B1844, DTCDECODE.

