

ACURA B1846: POWER SEAT FRONT UP-DOWN SWITCH CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$75-\$300
Can I Still Drive?	:	Yes

What Does The Acura B1846 Code Mean?

Power Seat Front Up-Down Switch Circuit malfunction.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B1846 Code?

- Check for loose or poor connections
- "Short" to ground or "Open" condition
- Faulty Power Seat Control Unit
- Faulty Power Seat Adjustment Switch

Reference Sources

[Acura B1846](#), DTCDECODE.