

ACURA B1955: REAR MICU LOST COMMUNICATION WITH MICU (MICU MESSAGE)

OVERVIEW

| | | |
|----------------------|---|------------------------------------|
| Severity | : | <div><div>Medium</div></div> |
| DIY Difficulty Level | : | <div><div>Intermediate</div></div> |
| Repair Cost | : | \$75-\$200 |
| Can I Still Drive? | : | Yes |

What Does The Acura B1955 Code Mean?

Poor communication between the Rear Fuse/Relay Box and the MICU.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

If DTCs [B1055](#), [B1056](#), [B1057](#), [B1157](#), [B1159](#), [B1180](#), [B1255](#), [B1955](#), [B2155](#), [B2156](#), and/or [B2161](#) are indicated, perform the MICU input test.

If no codes are present, perform the rear MICU input test.

What Are The Potential Causes Of The Acura B1955 Code?

- Loose or poor connections between the Rear Fuse/Relay Box and the MICU
- Blown fuse in the main under-hood fuse box
- Blown fuse in the under-dash fuse/relay box
- "Open" or "Short" Condition between the Rear Fuse/Relay Box and the MICU
- Faulty MICU Under-Dash Fuse/Relay Box.
- Faulty Rear Fuse/Relay Box and the MICU

Reference Sources

[Acura B1955](#), DTCDECODE.