

ACURA B2177: FRONT PASSENGER'S POWER WINDOW MOTOR PULSE A ERROR

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$250-\$510
Can I Still Drive?	:	Yes

What Does The Acura B2177 Code Mean?

Front Passenger's Power Window Motor malfunction.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B2177 Code?

- Check for loose or poor connections
- "Open" or "Short" Condition between Front Passenger's Power Window Motor and the Front Passenger's MPCS unit
- Faulty Front Passenger's Power Window Motor
- Faulty Front Passenger's MPCS unit

Reference Sources

[Acura B2177](#), DTCDECODE.