

## ACURA B2183: LEFT POWER MIRROR VERTICAL SENSOR SIGNAL ERROR

### OVERVIEW

Severity	:	<div>High</div>
DIY Difficulty Level	:	<div>Intermediate</div>
Repair Cost	:	\$150-\$400
Can I Still Drive?	:	Yes

### What Does The Acura B2183 Code Mean?

Left Power Mirror malfunction (Vertical)

**NOTE:** If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

### What Are The Potential Causes Of The Acura B2183 Code?

- Check for loose or poor connections
- "Open" or "Short" condition between the Left Power Mirror and the Driver's MPCS unit
- Faulty Driver's MPCS unit
- Faulty Left Power Mirror

### Reference Sources

[Acura B2183](#), DTCDECODE.